

## Birchmeier IRIS 15 AT3 New Generation Backpack Diagram

Reference Number	Item Description	Birchmeier Part Number	Arborchem Part Number
1	Birchmeier Lid With Gasket	103-972-02	20093
2	Lid Gasket	144-129-01	20122
3	Lid Strainer	770-096-99	20140
4	Tank Tube Suction Elbow	109-623-01	20111
5	Viton O-Ring (Only available in kit)	108-559-01V	20102
6	Brass Tank Nipple	120-013-01	NPN
7	Viton O-Ring (Only available in kit)	108-559-01V	20102
8	Anti-twist device	120-014-01	NPN
9	Brass Nut	120-012-01	NPN
10/28	Filter Screen	108-283-01	20533
11	Viton O-Ring (Only available in kit)	108-559-01V	20102
12	Central Bolt Complete	120-537-01	NPN
13	Pump Complete <b>without Piston</b> (Contains 11, 12, 13, 14, 15, 16, 17, 18, 38)	120-546-01	NPN
14	Spray Wand Carrier Attachement	120-016-01	NPN
15	Viton O-Ring (Only available in kit)	108-559-01V	20102
16	Check Valve	113-885-01	20117
17	Viton O-Ring (Only available in kit)	108-559-01V	20102
18	Valve Casing (Contains 11, 12, 14, 38)	120-574-01	NPN
19	Piston Assembly	110-512-03	20114
20	Piston Plunger	262-003-01	20126
21	Back Pack Straps (Left and Right)	120-549-01	20535
22	Pump Lever Complete (Contains 23)	120-544-01	NPN
23	Handle for Pump Levcer	120-614-01	NPN
24	Hose End Gasket	140-080-01	20120
25	Complete Hose Assembly	103-960-08	20091
26	Cut-off Handle Assembly Complete (Contains 27, 28, 29, 30, 31,32, 33, 34)	120-475-01	NPN
27	Black Plastic Handle	103-922-01	20090
28/10	Filter Screen	108-283-01	20533
29	O-ring for Brass Valve Cut-off Repair kit (Contains 24, 28, 29, 30, 31, 32, 34, 36)	106-002-01	20098
30	O-ring for Brass Valve Cut-off Repair kit (Contains 24, 28, 29, 30, 31, 32, 34, 36)	106-002-01	20098

31	Valve Stem Brass Valve Cut-off Repair kit (Contains 24, 28, 29, 30, 31, 32, 34, 36)	106-002-01	20098
32	Valve Packing Brass Valve Cut-off Repair kit (Contains 24, 28, 29, 30, 31, 32, 34, 36)	106-002-01	20098
33	Lever for Brass Valve Trigger	120-465-01	NPN
34	O-ring for Brass Valve Cut-off Repair kit (Contains 24, 28, 29, 30, 31, 32, 34, 36)	106-002-01	20098
35	Curved Brass Wand (No Tip)	120-074-01	20116
36	Wand Tip Gasket (Can be purchased in Brass Valve Repair kit)	140-080-01	20120
38	Grease Piston Cup	108-652-01	20103
39/40	Adjustable Nozzle	285-025-098	20128

